

#### General installation instructions for Anti-Static FlexCord:

For optimal effect place the Anti-Static FlexCord tautly across and approximately ¼" to ½" above or below moving web, sheets or conveyor (do not exceed 1"). Make sure the FlexCord is grounded.



## Typical mounting using mounting magnets (included) Step 1.

Using one magnet thread FlexCord through magnet and loosely double knot the end of FlexCord on the magnet side.



#### Step 2.

Pull FlexCord until knot catches inside the magnet. If need be trim excess cord. Mount to one side of the metallic machine frame.





#### Step 3.


Stretch the FlexCord tautly across and above or below the surface to be static neutralized. Using a second magnet repeat Steps 1 and 2. If needed, leave extra cord on the magnet side for grounding (see grounding methods in next section).

### **Grounding methods options:**

The FlexCord should be grounded. There are numerous ways of achieving this:









method 1



## Hints for installation and usage:

- 1) Rule of thumb: Position the FlexCord just prior to where the static charge is creating a production or quality problem.
- 2) It may be necessary to mount FlexCord at several points in a machine process. For example the feed and the delivery end of a printer.
- Depending on the application it may be necessary to mount the FlexCord above and below the web, sheets, etc to thoroughly control the static charge on the material.
- 4) Replace FlexCord when it has become matted or badly contaminated with inks, dust or other contaminants that will affect its performance.

# INSTRUCTIONS